



4141 W. CHANDLER BOULEVARD • CHANDLER, AZ 85226 • USA
PHONE (602) 961-1001 FAX (602) 961-1514

May 12, 1995

TO ALL EXEC 162F BUILDERS
with
RI 162F ENGINE SERIAL NUMBERS 6001 through 6030
EXEC 162F MANDATORY COMPLIANCE BULLETIN M-12

THIS BULLETIN IS MANDATORY AND MUST BE COMPLIED WITH

History: The ignition sensors originally supplied with your RI 162F engine may have a manufacturing defect which could cause the sensor to malfunction.

Action: DO NOT OPERATE YOUR HELICOPTER WITH THE FAULTY IGNITION SENSORS. Remove the defective sensors and send them to RotorWay International. They will be replaced at no cost to you with sensors of the correct type.

The NEW sensors can be identified by a short yellow band around the wires. DO NOT OPERATE YOUR HELICOPTER UNLESS THIS YELLOW BAND IS PRESENT ON THE IGNITION SENSOR WIRES.