

JUNE 16, 2005

**TO ALL EXEC, EXEC 90 AND EXEC 162F OWNERS**

**CAM GEAR SERVICE LETTER**

Mandatory bulletin M-14 and advisory bulletin A-30 were issued in January of 1997 requiring that the aluminum cam gear in the engine be replaced every 250 hours. Starting with engine number 6353, built in June of 1999, both of the timing gears have been made of steel. At approximately the same time the steel gears were supplied for parts requests for compliance to the bulletins. With the experience of service RotorWay International has raised the replacement time of the steel timing gears from 250 hours to 400 hours. RotorWay will continue to evaluate the serviceability of the timing gears for further increases in service life.